Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-0104**

Resource Identification

Property Name(s): ..... Elton House {Current}
Property Date: 1850
Address(s): ..... 1225 Route 608 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior end	Brick	
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Porch	Porch - 1-story, 3-bay	Wood	other

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling
Est. Date of Construction: .... 1850 ca {VDHR Survey File}
Accessed? .....
Primary Resource? ..... Yes
Number of Stories: 2.0
Architectural Style: ..... Other
Condition: .....
Interior Plan Type: ..... Central Passage, Single Pile
Threats to Resource: .....

Description: Architecture Summary: 2/2 windows on gable end. Simple window and cornice moldings. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: I-house End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Significance Statement: Appears to be a typical late 19th century I house with interior stove l chimneys. However, steep roof and offset gable-end windows may l indicate that this is an earlier house reworked in the late 19th l century.

Bibliographic Documentation

Report generated 11/17/04

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0104**

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: ..... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-104
Negative no(s).

City/Town/Village/Hamlet Windsor Vicinity
Street address or route number 1225 Rte. 608
Historic name
County Isle of Wight
U.S.G.S. Quad Windsor
Common name Elton House

Present use Dwelling
Original use Dwelling
Building Style Vernacular
Building Date(s) 2nd half of 19th century

1. Construction Materials

- [x] wood frame
- [ ] brick
  - bond: [ ] English [ ] Flemish [ ] ____-course American [ ] stretcher [ ] other ____
- [ ] stone
  - [ ] random rubble [ ] coursed rubble [ ] ashlar [ ] dressed [ ] rock-faced
- [ ] log:
  - [ ] squared [ ] unsquared
  - notching: [ ] V-notch [ ] saddle [ ] square [ ] half dovetail [ ] full dovetail [ ] diamond
- [ ] concrete block
- [ ] terra cotta
- [ ] steel frame
- [ ] other ____

2. Cladding Material

- [ ] weatherboard
- [ ] vertical siding
- [ ] board & batten
- [ ] shingle: [ ] wood [ ] asbestos [ ] asphalt
- [x] bricktex
- [ ] other ____
- [ ] composition siding
- [ ] stucco
- [ ] aluminum or vinyl siding
- [ ] cast iron
- [ ] sheet metal
- [ ] enameled metal
- [ ] glass



3. Stories (number) 2
- [ ] low basement
- [ ] raised basement

4. Bays (number): front 3 side (church) ____
- [ ] symmetrical
- [ ] asymmetrical

5. Roof Type

- [ ] shed
  - [ ] parapet?
- [x] gable
  - [ ] pediment?
  - [ ] parapet?
  - [ ] clipped end?
  - [ ] cross gable?
  - [ ] central front gable?
- [ ] hipped
  - [ ] pyramidal?
- [ ] mansard
- [ ] false mansard
- [ ] gambrel
- [ ] flat
  - [ ] parapet?
- [ ] roof not visible
- [ ] other ____

6. Roofing Material

- [ ] shingle
  - [ ] composition (asphalt, asbestos, etc.)
  - [ ] wood
- [x] metal
  - [x] standing seam
  - [ ] corrugated
  - [ ] pressed tin (simulated shingles)
- [ ] tile
  - [ ] pantile [ ] flat [ ] glazed
- [ ] slate
- [ ] not visible

7. Dormers (number): front ____ side ____
- [ ] gable [ ] pediment?
- [ ] shed
- [ ] hipped

8. Primary Porch
style ____
stories 1
levels 1 bays 3
materials wood, standing-seam metal
description and decorative details
Chamfered wood columns, hipped roof.

9. General supplementary description and decoration: Six-over-six sash front wall, two-over-two on gable end. Cornice returns on gable ends. Simple window and cornice moldings.

10. Major additions and alterations:

11. Outbuildings:

12. Landscape Features: Two large oak trees in yard.

13. Significance: Appears to be a typical late 19th-C I house with interior stove chimneys. However, steep roof and offset gable-end windows may indicate that this is an earlier house reworked in the late 19th century.

Surveyed by: Willie Graham Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey